


Sommario

1. Connection examples	3
<i>CANbus</i>	3
<i>Digital inputs</i>	4
<i>PNP / Push Pull count inputs</i>	5
<i>Voltmetric and amperometric analog inputs</i>	6
<i>Voltmetric and potentiometric analog inputs</i>	7
<i>Protected digital outputs</i>	8
<i>Analog outputs</i>	9


1. Connection examples

CANbus





	<ul style="list-style-type: none">On the first (1) and on the last (3) device of the chain, the termination resistances must be inserted.The cable shoes must be connected to ground by the fastons provided on the metal body.
	<ul style="list-style-type: none">To activate the internal termination resistance see paragraph Setup of CAN1 and CAN2 PORT Termination resistances


Digital inputs




PNP / Push Pull count inputs




Voltmetric and amperometric analog inputs

Voltmetric and potentiometric analog inputs

Protected digital outputs



Analog outputs



Documento generato automaticamente da **Qem Wiki** - <https://wiki.qem.it/>

Il contenuto wiki è costantemente aggiornato dal team di sviluppo, è quindi possibile che la versione online contenga informazioni più recenti di questo documento.